

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:

OGM Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0150007
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, January 12, 2010
Start Date/Time:	1/12/2010 8:00:00 AM
End Date/Time:	1/12/2010 1:30:00 PM
Last Inspection:	Tuesday, December 15, 2009

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Partly Cloudy, Temp. 7 Deg. F.

InspectionID Report Number: 2242

Accepted by: jhelfric

1/25/2010

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO MID-CONTINENT REGION

Site: HIDDEN VALLEY MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	960.00	
Total Disturbed	6.70	
Phase I	6.70	
Phase II		
Phase III		

Mineral Ownership

Other

☐ Federal State County Fee

Surface

Loadout
Processing
Reprocessing

✓ Underground

Types of Operations

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Road is snow covered. County road to site had not been plowed. Road passable by use of four wheel drive.

Jaren Joregensen Consol was present during the inspection.

Inspector's Signature:

Date

Tuesday, January 12, 2010

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Tuesday, January 12, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	Roads: Construction, Maintenance, Surfacing	✓		✓	
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Tuesday, January 12, 2010

Page 3 of 3

2. Signs and Markers

The mine ID sign is in place at the point of public access and contains the required information. Sign is old and has bullet holes, but remains legible

4.a Hydrologic Balance: Diversions

Area is blanketed by snow. Diversion is snow covered.

16.a Roads: Construction, Maintenance, Surfacing

Roads are snow covered and require the use of four wheel drive to access the site.